

# Gunnersbury Park – High Priority works 2010. Page 1

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/12 (53644)	Robinia pseudoacacia	13.0m	59cm	Poor	Dead wood >30mm	Deadwood
Sgl/17 (53664)	Populus nigra 'Betulifolia'	16.0m	113cm	Good	Large, heavy branches Dead wood >30mm	Crown Reduce 25%
Sgl/21 (53680)	Populus nigra 'Betulifolia'	17.0m	101cm	Good	Large, heavy branches Dead wood >30mm	Crown Reduce 30%
Sgl/22 (53684)	Populus nigra 'Betulifolia'	15.0m	60cm	Good	Lean (more than 20%)	Fell Tree - tree leans at acute angle over driveway
Sgl/23 (53688)	Populus nigra 'Betulifolia'	13.0m	68cm	Fair	Hanging broken branch Broken\lost leader - cavity from lost leader Dead wood >30mm	Pollard
Sgl/24 (53692)	Populus nigra 'Betulifolia'	12.0m	35cm	Fair	Lean (more than 20%) Dead wood >30mm	Fell Tree
Sgl/26 (53700)	Fraxinus excelsior	11.0m	59cm	Fair	Dead wood >30mm	Deadwood
Sgl/32 (53724)	Fraxinus excelsior	12.0m	65cm	Fair	Cavity in stem - 5m up main trunk and at 6m Dead wood >30mm	Pollard
Sgl/33 (53728)	Platanus x hispanica	12.0m	65cm	Good	Bark wound over 20% of stem - wound in central leader Cavity in stem - at crown break from large limb lost	Crown Reduce 25%
Sgl/108 (54028)	Prunus avium	7.5m	38cm	Poor	Cavity in stem - cavities at main crown break Dying Dead wood >30mm	Fell Tree

## Gunnersbury Park – High Priority works 2010. Page 2

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/120 (54076)	Robinia pseudoacacia	6.5m	29cm	Poor	Dying Dead wood >30mm Multi-stemmed	Coppice
Sgl/146 (54184)	Crataegus monogyna	6.5m	44cm	Poor	Main stem rot	Fell Tree
Sgl/162 (54248)	Acer platanoides	13.0m	70cm	Poor	Cavity in stem Main stem rot	Fell Tree
Sgl/170 (54280)	Acer pseudoplatanus	14.0m	40cm	Fair	Splits in major limb/crotch/trunk - split /tear 10m up main stem	Crown Reduce 30%
Sgl/187 (54348)	Unknown Species - Broadleaf	15.0m	62cm	Fair	Trunk or branch cankers Dead wood >30mm	Climbing Inspection Deadwood
Sgl/189 (54356)	Acer pseudoplatanus	15.0m	40cm	Poor	Extention growth poor Dead wood >30mm Stressed: tree can recover	Deadwood
Sgl/249 (54600)	Carpinus betulus	12.0m	25cm	Poor	Lean (more than 20%) Dead wood >30mm	Fell Tree
Sgl/262 (54652)	Acer pseudoplatanus	17.0m	65cm	Good	Hanging broken branch Dead wood >30mm	Deadwood
Sgl/263 (54656)	Acer pseudoplatanus	16.0m	51cm	Good	None recorded..	Deadwood

## Gunnersbury Park – High Priority works 2010. Page 3

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/270 (54684)	Aesculus hippocastanum	13.0m	86cm	Poor	Bark wound over 20% of stem  Forks at <1.5m Dead wood >30mm  Narrow forks with included bark Codominant stems - 3 stems	Fell Tree
Sgl/278 (54716)	Aesculus hippocastanum	16.0m	61cm	Poor	Large branches lost recently Cracked & lifting bark Main stem rot	Pollard
Sgl/281 (54728)	Aesculus hippocastanum	12.0m	33cm	Poor	Dying  Dead wood >30mm Main stem rot Lean (more than 20%) Dead wood >30mm	Fell Tree
Sgl/315 (54872)	Aesculus hippocastanum	17.0m	81cm	Fair	Cavity in stem - 5m up stem	Crown Reduce 25%
Sgl/322 (54900)	Aesculus species	11.0m	30cm	Poor	Dead wood >30mm	Fell Tree
Sgl/328 (54924)	Fraxinus excelsior	15.0m	56cm	Fair	Cavity in stem - paraqueets nesting 8m up main stem  Fungal fruiting bodies - old fruiting bodies, blackened charcoal  like, possible inonotus hispidus	Climbing Inspection

## Gunnersbury Park – High Priority works 2010. Page 4

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/329 (54928)	Fraxinus excelsior	15.0m	53cm	Fair	Fungal fruiting bodies - old fruiting bodies on main stem Dead wood >30mm	Deadwood
Sgl/336 (54956)	Aesculus hippocastanum	8.5m	40cm	Poor	Cavity in stem - 4m up stem  Cracked & lifting bark	Fell Tree
Sgl/341 (54976)	Robinia pseudoacacia	14.0m	60cm	Poor	Die back  Dead wood >30mm Dead wood >30mm	Pollard
Sgl/371 (55096)	Populus canescens	25.0m	104cm	Fair	Hanging broken branch  Dead wood >30mm	Pollard
Sgl/372 (55100)	Populus canescens	13.0m	79cm	Fair	Hanging broken branch  Dead wood >30mm  Regrown pollard or topped tree	Pollard
Sgl/376 (55116)	Populus canescens	25.0m	94cm	Fair	Cavity in stem - small nesting cavities , paraqueets Dead wood >30mm	Pollard Climbing Inspection
Sgl/453 (55428)	Robinia pseudoacacia	10.0m	49cm	Poor	Wind-thrown or rock - resting on adjacent sycamore	Fell Tree
Sgl/466 (55480)	Fraxinus excelsior	12.0m	40cm	Good	Ivy Restricting Inspection  Ivy or climbing plants Dead wood >30mm	Deadwood Girdle Ivy
Sgl/475 (55516)	Robinia pseudoacacia	10.0m	63cm	Dead	Wind-thrown or rock - laying on ground	Branch Removal - clear from over path and off adjacent plane tree
Sgl/477 (55524)	Unknown Species - Broadleaf	12.0m	30cm	Dead	Dead	Fell Tree

## Gunnersbury Park – High Priority works 2010. Page 5

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/479 (55532)	Tilia species	16.0m	49cm	Fair	Basal rot Lean (more than 20%) Splits in major limb/crotch/trunk	Fell Tree
Sgl/504 (55632)	Aesculus hippocastanum	9.0m	30cm	Poor	Hanging broken branch Poor Form	Fell Tree
Sgl/544 (55792)	Tilia x europaea	25.0m	36cm	Fair	Basal rot Epicormic growth on trunk	Deadwood Pollard
Sgl/578 (55928)	Aesculus hippocastanum	26.0m	108cm	Poor	Cavity in stem - old pruning wound Large, heavy branches Dead wood >30mm Codominant stems	Pollard
Sgl/579 (55932)	Aesculus hippocastanum	23.0m	87cm	Fair	Dead wood >30mm Regrown pollard or topped tree Codominant stems	Pollard
Sgl/592 (55984)	Aesculus hippocastanum	14.0m	106cm	Poor	Dying Extention growth poor Fungal fruiting bodies - old meripilus at base Regrown pollard or topped tree	Pollard

## Gunnersbury Park – High Priority works 2010. Page 6

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/629 (56132)	Aesculus hippocastanum	23.0m	91cm	Fair	Large branches lost recently Fungal fruiting bodies - 12m up at main fork Dead wood >30mm Stressed: tree can recover	Pollard
Sgl/630 (56136)	Aesculus hippocastanum	24.0m	97cm	Fair	Hanging broken branch  Regrown pollard or topped tree  Truncated branches or pruning stubs	Pollard
Sgl/647 (56204)	Fagus sylvatica	16.0m	82cm	Poor	Die back  Dying Fungal fruiting bodies - Ganoderma pfeifferi Dead wood >30mm	Monolith
Sgl/683 (56364)	Acer platanoides	22.0m	91cm	Fair	Crown rot - main limb facing lake , fungus present	Branch Removal - remove dying limb  Crown Balance - balance rest of crown after limb has been removed
Sgl/705 (56472)	Salix fragilis	13.0m	82cm	Fair	Cavity in stem  Regrown pollard or topped tree	Pollard
Sgl/706 (56476)	Prunus spinosa	7.0m	13cm	Dead	Dead	Fell Tree

## Gunnersbury Park – High Priority works 2010. Page 7

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/710 (56496)	Prunus species	5.0m	13cm	Dead	Dead Wind-thrown or rock	Fell Tree
Sgl/731 (56596)	Salix fragilis	23.0m	90cm	Fair	Hanging broken branch Dead wood >30mm Narrow forks with included bark Codominant stems	Pollard
Sgl/807 (56940)	Laburnum anagyroides	8.0m	37cm	Dead	Dead	Fell Tree
Sgl/868 (57184)	Robinia pseudoacacia	18.0m	22cm	Poor	Dying	Fell Tree
Sgl/874 (69008)	Quercus palustris	20.0m	89cm	Good	Imbalanced crown Lean (more than 20%) Dead wood >30mm	Climbing Inspection - inspect cavity Deadwood
Sgl/880 (69032)	Acer	24.0m	36cm	Poor	Major cavity over 10% of stem Dead wood >30mm	Monolith
Sgl/900 (69116)	Tilia petiolaris	20.0m	38cm	Poor	Splits in major limb/crotch/trunk - at main fork Codominant stems	Pollard - below split
Sgl/902 (69124)	Aesculus hippocastanum	30.0m	90cm	Good	Cracked & lifting bark - in crown Codominant stems	Climbing Inspection Crown Reduce 30%
Sgl/916 (69180)	Acer pseudoplatanus	28.0m	64cm	Good	Hanging broken branch Dead wood >30mm	Deadwood

## Gunnersbury Park – High Priority works 2010. Page 8

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/957 (69344)	Acer pseudoplatanus	25.0m	42cm	Fair	Bark wound over 20% of stem - on righthand codominate stem Dead wood >30mm Codominant stems	Fell Tree - fell right hand stem with wound on
Sgl/984 (69452)	Acer pseudoplatanus	15.0m	30cm	Good	Hanging broken branch Dead wood >30mm	Deadwood
Sgl/1005 (69540)	Aesculus flava	15.0m	90cm	Fair	Trunk or branch cankers Dead wood >30mm	Fell Tree
Sgl/1009 (69556)	Aesculus hippocastanum	24.0m	130cm	Good	Bark congestion/stretch/loosening Dead wood >30mm	Branch Removal - bark wound on first limb up main stem overhanging path , reduce weight from limb
Sgl/1051 (69724)	Acer pseudoplatanus	20.0m	63cm	Good	Dead wood >30mm Dead wood >30mm	Pollard
Sgl/1075 (69828)	Fagus sylvatica	28.0m	83cm	Good	Hanging broken branch Cavity in stem - small cavity in stem 11m up main stem Dead wood >30mm	Climbing Inspection - inspect cavity Deadwood
Sgl/1121 (70028)	Acer pseudoplatanus	17.0m	65cm	Fair	Major cavity over 10% of stem Dead wood >30mm	Pollard
Sgl/1122 (70032)	Acer pseudoplatanus	18.0m	81cm	Poor	Cavity in stem Die back	Pollard

## Gunnersbury Park – High Priority works 2010. Page 9

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1124 (70040)	Acer pseudoplatanus	19.0m	64cm	Fair	Bark wound over 20% of stem Cavity in stem Cracked & lifting bark Dead wood >30mm	Climbing Inspection - inspect cavity 8m up main stem Crown Reduce 25%
Sgl/1133 (70080)	Aesculus hippocastanum	14.0m	47cm	Poor	Dead wood >30mm Main stem rot	Fell Tree Stump Treatment
Sgl/1148 (70140)	Acer pseudoplatanus	27.0m	81cm	Fair	Cavity in stem - at crown break Extention growth poor Fungal fruiting bodies - old inonotus at base Dead wood >30mm	Climbing Inspection Deadwood
Sgl/1151 (70152)	Quercus robur	30.0m	119cm	Good	Dead wood >30mm	Deadwood
Sgl/1216 (70416)	Prunus avium	12.0m	43cm	Poor	Dying Dead wood >30mm	Pollard
Sgl/1272 (70668)	Acer pseudoplatanus 'Brilliantissimum'	19.0m	60cm	Good	Splits in major limb/crotch/trunk - split in first major limb 6m up main stem , overhanging footpath and bus stop	Branch Removal - remove split limb
Sgl/1283 (70712)	Acer pseudoplatanus	22.0m	94cm	Fair	Hanging broken branch Dead wood >30mm	Fell Tree
Sgl/1286 (70724)	Platanus x hispanica	25.0m	75cm	Good	Cavity in stem - cavity in limb over footpath , 16m up main stem Fungal fruiting bodies - old inonotus on limb with cavity	Climbing Inspection

## Gunnersbury Park – High Priority works 2010. Page 10

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1287 (70728)	Platanus x hispanica	25.0m	63cm	Good	Cavity in stem - 18m up stem	Climbing Inspection
Sgl/1288 (70732)	Platanus x hispanica	25.0m	78cm	Fair	Cavity in stem - 18m up main stem , large branch lost	Crown Reduce 25%
Sgl/1292 (70748)	Castanea sativa	19.0m	80cm	Poor	Dead wood >30mm	Deadwood
Sgl/1302 (70788)	Acer pseudoplatanus	29.0m	86cm	Fair	Dead wood >30mm Thinning Crown	Deadwood
Sgl/1315 (70840)	Aesculus hippocastanum	27.0m	76cm	Fair	Major cavity over 10% of stem	Pollard
Sgl/1334 (70916)	Platanus x hispanica	28.0m	93cm	Fair	Basal rot Die back	Pollard
Sgl/1354 (70996)	Aesculus hippocastanum	17.0m	50cm	Poor	Cracked & lifting bark Dying	Fell Tree Stump Treatment
Sgl/1355 (71000)	Aesculus hippocastanum	18.0m	53cm	Poor	Cracked & lifting bark Dying	Fell Tree Stump Treatment
Sgl/1413 (71232)	Populus nigra 'Betulifolia'	27.0m	91cm	Fair	Bark wound over 20% of stem - 14m up main stem from lostbranch Cavity in stem - small cavities with nesting birds up main stem , plus larger cavities from old pruning wounds	Monolith Climbing Inspection
Sgl/1428 (71292)	Quercus ilex	20.0m	77cm	Fair	Major cavity over 10% of stem	Crown Lift - lift over path and off building , aim is to reduce weight

## Gunnersbury Park – High Priority works 2010. Page 11

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1507 (71612)	Prunus avium	13.0m	38cm	Fair	Cavity in stem Main stem rot	Monolith
Sgl/1511 (71628)	Prunus avium	10.0m	27cm	Poor	Dying Fungal fruiting bodies - ganoderma all over stem	Monolith
Sgl/1533 (71716)	Crataegus monogyna	13.0m	63cm	Poor	Hanging broken branch - resting in golf course Cavity in stem	Monolith
Grp/48 (71752)	Mixed broadleaves	18.0m	32cm	Fair	Hanging broken branch Broken branch(es) Bark wound over 20% of stem - squirrel damage Dead wood >30mm	Clean Out
Sgl/1572 (71876)	Populus nigra 'Betulifolia'	19.0m	80cm	Fair	Hanging broken branch Broken branch(es) - resting on fence , Regrown pollard or topped tree	Branch Removal - remove hanging branch from crown and remove branch off fence, both can stay on the ground for habitat Pollard - low priority
Sgl/1582 (71920)	Betula pubescens	14.0m	13cm	Dead	Dead	Fell Tree
Sgl/1584 (71928)	Quercus robur	30.0m	111cm	Good	Dead wood >30mm	Deadwood
Sgl/1585 (71932)	Aesculus hippocastanum	16.0m	30cm	Poor	Dying Dead wood >30mm	Fell Tree Stump Treatment

## Gunnersbury Park – High Priority works 2010. Page 12

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1596 (71976)	Platanus x hispanica	17.0m	38cm	Fair	Splits in major limb/crotch/trunk Codominant stems	Fell Tree Stump Treatment
Sgl/1597 (71984)	Taxus baccata	15.0m	45cm	Good	None recorded..	Crown Lift - off building
Sgl/1600 (72000)	Tilia species	30.0m	108cm	Good	Branch/trunk seam - starts 5m from ground stem Truncated branches or pruning stubs	Climbing Inspection
Sgl/1634 (72136)	Larix decidua	18.0m	45cm	Good	Bark wound over 20% of stem - 11m up stem	Climbing Inspection
Sgl/1645 (72180)	Morus nigra	6.0m	28cm	Poor	Major cavity over 10% of stem Regrown pollard or topped tree Important landscape tree	Crown Reduction - remove to main branches down to lower growth and cavity
Sgl/1652 (72212)	Corylus avellana	12.0m	45cm	Poor	Basal rot Cavity in stem Multi-stemmed	Coppice Fell Tree Stump Treatment
Sgl/1656 (72228)	Crataegus species	11.0m	42cm	Fair	Major cavity over 10% of stem	Fell Tree
Sgl/1660 (72244)	Acer	15.0m	57cm	Fair	Bark wound over 20% of stem - small wounds over crown Dead wood >30mm	Clean Out
Sgl/1661 (72248)	Malus species	9.0m	44cm	Fair	Imbalanced crown Lean (more than 20%) Narrow forks with included bark	Crown Balance Deadwood

## Gunnersbury Park – High Priority works 2010. Page 13

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1669 (72280)	Unknown Species - Broadleaf	15.0m	72cm	Fair	Codominant stems Hanging broken branch Narrow forks with included bark Codominant stems	Crown Lift Clean Out
Sgl/1671 (72288)	Quercus rubra	20.0m	98cm	Good	Dead wood >30mm	Deadwood
Sgl/1673 (72296)	Quercus rubra	20.0m	106cm	Good	Dead wood >30mm	Deadwood
Sgl/1674 (72300)	Quercus rubra	20.0m	94cm	Good	Dead wood >30mm	Deadwood
Sgl/1718 (72480)	Quercus rubra	15.0m	60cm	Fair	Die back Dead wood >30mm	Deadwood
Sgl/1725 (72512)	Quercus rubra	24.0m	126cm	Good	Dead wood >30mm	Deadwood
Sgl/1727 (72520)	Carpinus betulus	15.0m	33cm	Fair	Bark wound over 20% of stem	Fell Tree
Sgl/1751 (72616)	Castanea sativa	24.0m	151cm	Fair	Dead wood >30mm	Deadwood
Sgl/1752 (72620)	Morus nigra	5.0m	62cm	Poor	Basal rot  Splits in major limb/crotch/trunk - tree has split out laying on the ground	Fell Tree
Sgl/1761 (72656)	Quercus cerris	18.0m	92cm	Fair	Die back Lean (more than 20%) Dead wood >30mm	Deadwood
Sgl/1767 (72680)	Fraxinus excelsior	24.0m	73cm	Fair	Ivy Restricting Inspection	Climbing Inspection

## Gunnersbury Park – High Priority works 2010. Page 14

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
					Dead wood >30mm	Deadwood
Sgl/1795 (72792)	Acer negundo	15.0m	34cm	Fair	Major cavity over 10% of stem	Fell Tree
Sgl/1805 (72832)	Taxus baccata	12.0m	48cm	Good	Lean (more than 20%) Wind-thrown or rock	Crown Reduction - reduce weight to compensate for uprooting
Sgl/1806 (72836)	Taxus baccata	7.0m	26cm	Good	Lean (more than 20%)	Crown Lift
Sgl/1807 (72840)	Taxus baccata	7.0m	19cm	Good	Lean (more than 20%)	Crown Lift
Sgl/1823 (72904)	Cedrus atlantica glauca	20.0m	101cm	Good	Large branches lost recently Large, heavy branches	Crown Reduction - reduce weight on larger limbs
Sgl/1824 (72908)	Chamaecyparis lawsoniana	10.0m	0cm	Good	Multi-stemmed	Branch Removal - one limb bending over remove
Sgl/1829 (72928)	Ilex aquifolium	6.0m	16cm	Good	Lean (more than 20%)	Crown Balance - reduce weight
Sgl/1846 (72996)	Salix fragilis	6.0m	42cm	Dead	Dead	Fell Tree
Sgl/1861 (73056)	Unknown Species - Broadleaf	4.0m	9cm	Good	Lean (more than 20%)	Fell Tree
Sgl/1873 (73108)	Robinia pseudoacacia	16.0m	69cm	Poor	Dying Dead wood >30mm	Monolith
Sgl/1876 (73120)	Tilia platyphyllos	16.0m	72cm	Good	Basal and trunk suckers Dead wood >30mm	Clean Out
Sgl/1879 (73132)	Tilia x europaea	15.0m	64cm	Good	Dead wood >30mm	Deadwood
Sgl/1881 (73140)	Tilia x europaea	16.0m	61cm	Good	Dead wood >30mm	Deadwood
Sgl/1883 (73148)	Tilia platyphyllos	19.0m	71cm	Good	Dead wood >30mm	Deadwood

## Gunnersbury Park – High Priority works 2010. Page 15

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1885 (73156)	Aesculus hippocastanum	17.0m	87cm	Fair	Dead wood >30mm Poor Form	Deadwood
Sgl/1889 (73172)	Aesculus hippocastanum	20.0m	87cm	Good	Large branches lost recently Bark wound over 20% of stem Cavity in stem - 3m up main stem Dead wood >30mm	Pollard
Sgl/1919 (73300)	Cedrus atlantica glauca	18.0m	75cm	Good	Hanging broken branch Dead wood >30mm	Deadwood
Sgl/1920 (73304)	Cedrus atlantica glauca	18.0m	65cm	Good	None recorded..	Deadwood
Sgl/1941 (73396)	Prunus cerasifera	9.0m	49cm	Fair	Fungal fruiting bodies - ganoderma Codominant stems	Fell Tree
Sgl/1942 (73400)	Ilex aquifolium	11.0m	29cm	Fair	Poor Form Thinning Crown	Fell Tree
Sgl/1965 (73496)	Cedrus atlantica	17.0m	96cm	Good	Large branches lost recently	Crown Lift - lift first branch over driveway , this will also reduce weight
Sgl/1984 (73576)	Morus alba	4.5m	30cm	Dead	Dead	Fell Tree Stump Treatment
Sgl/1987 (73588)	Unknown Species - Broadleaf	14.0m	53cm	Fair	Bark wound over 20% of stem Dead wood >30mm	Crown Lift 2.5m - over footpath Deadwood

## Gunnersbury Park – High Priority works 2010. Page 16

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/1991 (73604)	Acer pseudoplatanus	24.0m	40cm	Good	Ivy Restricting Inspection Ivy or climbing plants Multi-stemmed Narrow forks with included bark - bark wound in forks Extention growth poor	Climbing Inspection Girdle Ivy
Sgl/2037 (73788)	Catalpa bignonioides	12.0m	46cm	Good	Broken branch(es) - resting on wall	Branch Removal
Sgl/2049 (73836)	Magnolia species	7.0m	65cm	Poor	Basal rot Ivy Restricting Inspection Dead wood >30mm Codominant stems	Deadwood Girdle Ivy
Sgl/2070 (73920)	Quercus ilex	16.0m	84cm	Good	Cavity in stem Fungal fruiting bodies - ganoderma at base	Crown Reduction - with aim of reducing weight
Sgl/2080 (73960)	Taxus baccata	10.0m	83cm	Good	Bark wound over 20% of stem Dead wood >30mm	Clean Out
Grp/63 (74152)	Taxus baccata	10.0m	38cm	Good	None recorded..	Crown Lift - off neighbours property
Sgl/2136 (74192)	Robinia pseudoacacia	14.0m	48cm	Good	Ivy or climbing plants Dead wood >30mm	Girdle Ivy
Sgl/2149 (74252)	Cedrus atlantica	18.0m	130cm	Good	Hanging broken branch Cavity in stem - small cavity on limb overhanging putting green , 6m from ground Dead wood >30mm	Climbing Inspection - inspect cavity Clean Out

## Gunnersbury Park – High Priority works 2010. Page 17

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/2171 (74340)	Aesculus hippocastanum	13.0m	88cm	Dead	Dead	Monolith - to safe height
Sgl/2172 (74344)	Aesculus hippocastanum	13.0m	68cm	Dead	Dead	Monolith
Sgl/2182 (74388)	Populus canescens	25.0m	92cm	Fair	Cavity in stem - in main scaffold limb Dead wood >30mm	Pollard
Sgl/2183 (74392)	Populus canescens	18.0m	75cm	Dead	Dead	Fell Tree
Sgl/2190 (74420)	Cedrus atlantica	20.0m	102cm	Fair	Hanging broken branch Fungal fruiting bodies - small ganoderma at base Dead wood >30mm	Clean Out
Sgl/2209 (74500)	Acer saccharinum	30.0m	71cm	Fair	Large branches lost recently Basal and trunk suckers Regrown pollard or topped tree	Pollard
Grp/68 (74536)	Aesculus hippocastanum	14.0m	77cm	Poor	Trunk or branch cankers Dead wood >30mm Splits in major limb/crotch/trunk	Pollard
Sgl/2221 (74552)	Pinus wallichiana	16.0m	73cm	Fair	attached and resting on ground Cavity in stem - from lost branch Dense crown	Crown Reduction - balance crown
Sgl/2232 (74600)	Quercus robur	10.0m	78cm	Poor	Major cavity over 10% of stem	Monolith - half monolithed , make safe

## Gunnersbury Park – High Priority works 2010. Page 18

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/2234 (74608)	Quercus robur	18.0m	108cm	Good	Major cavity over 10% of stem - 7m up main stem	Climbing Inspection Crown Reduction - reduces weight
Sgl/2257 (74708)	Acer pseudoplatanus	22.0m	88cm	Good	Cavity in stem - small nesting cavity in stem 5m up Ivy Restricting Inspection Ivy or climbing plants Dead wood >30mm Codominant stems	Climbing Inspection Deadwood Girdle Ivy
Sgl/2261 (74724)	Acer pseudoplatanus	24.0m	94cm	Fair	Cavity in stem - small nesting cavities over crown Dead wood >30mm	Pollard Climbing Inspection
Sgl/2267 (74748)	Eucalyptus coccifera	7.0m	0cm	Poor	Multi-stemmed Wind-thrown or rock	Fell Tree
Sgl/2285 (74824)	Abies	11.0m	16cm	Fair	Major cavity over 10% of stem	Fell Tree
Sgl/2300 (74888)	Quercus rubra	21.0m	111cm	Good	Cavity in stem - small nesting cavities in crown Dead wood >30mm	Deadwood
Sgl/2317 (74960)	Quercus robur	20.0m	70cm	Good	Dead wood >30mm	Deadwood
Sgl/2318 (74964)	Quercus cerris	20.0m	76cm	Good	Dead wood >30mm	Deadwood
Sgl/2324 (74988)	Ilex aquifolium	13.0m	19cm	Dead	None recorded.. Bark wound over 20% of stem	Fell Tree
Sgl/2336 (75036)	Fagus sylvatica	17.0m	86cm	Fair	Die back Fungal fruiting bodies - old fruiting bodies on roots	Crown Reduce 25%

## Gunnersbury Park – High Priority works 2010. Page 19

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
Sgl/2340 (75052)	Tilia x europaea	19.0m	80cm	Good	Hanging broken branch Epicormic growth on trunk Dead wood >30mm	Deadwood
Sgl/2350 (75092)	Aesculus hippocastanum	18.0m	96cm	Fair	Cavity in stem - 4m up cavity from old pruning wound and 8m	Crown Reduce 25%
Sgl/2351 (75096)	Acer pseudoplatanus	15.0m	63cm	Fair	Extention growth poor Dead wood >30mm Thinning Crown	Deadwood
Sgl/2361 (75136)	Tilia platyphyllos	18.0m	76cm	Good	Dead wood >30mm	Deadwood
Sgl/2382 (75220)	Tilia x europaea	22.0m	72cm	Fair	Basal and trunk suckers Dead wood >30mm	Deadwood
Sgl/2393 (75264)	Acer pseudoplatanus	22.0m	65cm	Fair	Dead wood >30mm Thinning Crown	Deadwood
Sgl/2404 (75308)	Acer pseudoplatanus	23.0m	73cm	Fair	Cavity in stem - small nesting cavities Dead wood >30mm	Deadwood
Sgl/2429 (75408)	Acer pseudoplatanus	25.0m	74cm	Fair	Major cavity over 10% of stem	Pollard
Sgl/2443 (75464)	Aesculus hippocastanum	34.0m	138cm	Fair	Fungal fruiting bodies Large, heavy branches Dead wood >30mm Codominant stems	Climbing Inspection Crown Reduce 30%
Sgl/2469 (75568)	Platanus x hispanica	33.0m	156cm	Good	Cavity in stem - small nesting cavities in crown	Climbing Inspection

## Gunnersbury Park – High Priority works 2010. Page 20

Type/Seq/Code	Species	Height	Trunk	Phys Cond	Condition codes	Recommendations
					Splits in major limb/crotch/trunk - 20m up in crown	
Sgl/2489 (75648)	Tilia x europaea	28.0m	110cm	Good	Dead wood >30mm	Deadwood
Sgl/2490 (75652)	Tilia x europaea	23.0m	68cm	Good	Dead wood >30mm	Deadwood